




**QD-U10A**  
UNIVERSAL A/C CONTROL SYSTEM



UNIVERSAL A/C  
CONTROL SYSTEM

QD-U10A



- 1 There should be no strong light before the IR (infrared light receiver).
- 2 For split A.C., the stepper motor socket(MOTOR) has 6 pins. Two pins on both sides are common pins(12V). Either of them must be connect with the common pin of the stepper motor plug that has 5 pins. If stepper motor rotating direction is reversed, the common pin of the motor plug should be connect to be other common pin of the motor socket.

CE MADE IN CHINA


QD-U10A

UNIVERSAL A/C  
CONTROL SYSTEM



UNIVERSAL A/C CONTROL SYSTEM  
**QD-U10A**

**UNIVERSAL A/C CONTROL SYSTEM QD-U10A**



- 5 Working Mode
- 3 Fan Speed
- 2 Sensors
- Digital LED Display
- Prevent Cold Wind in Heating Mode
- Main Board With Base Holder

**QD-U10A**  
UNIVERSAL A/C CONTROL SYSTEM

⚠ Please install by certificated technician.  
Please test the system before installation.  
Please avoid strong light before IR receiver